

Sep. 30, 2003

Subject: Permissive Class II change for FCC ID: QTRWLC10001

Dear Sir,

The Wireless ISA module, Model No.: WLC-100M, FCC ID: QTRWLC10001 need to do the Class II change due to changing of the antenna. We evaluated that the changed would NOT affect the RF characteristics except for the Radiated Spurious Emission.

The product has conducted the Radiated Spurious Emission test and compliance with the CFR 47 Part 15 Subpart C 15.247 and relative regulations. For more details, please refer to the test report.

If you have any question, please feel free to contact me.

Best Regards,



Elton Chen
Assistants Manager
Intertek Testing Service Taiwan Ltd.