




VAP1200A External View, Side 1



VAP1200 External View, Side 2
Reverse TNC's - Disabled in initial VAP1200 Grant (FCC ID QTZVAP1200)

VAP1200A Left Side

This hole will not be present in the production version of the AP1200 A



VAP1200A Right Side

This hole will not be present in the production version of the VAP1200A





VAP1200A Bottom View