



Date: 27 February 2024

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, Maryland 21046

To Whom it May Concern:

We attest to the following:

- Per FCC KDB 905462 D03 v01r01, the device is a client device with no radar detection capability. The client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.
- Per FCC KDB 594280 D01 v02r01, the device complies with the requirements for software configuration control. The device meets the definition of FCC 15.202 client device and does not have the ability to be configured by end users or professional installers to operate outside the authorized bands
- Per FCC 15.407(c), the device will automatically discontinue transmission in case of either absence of information to transmit or operational failure.

Andrew Wingerter
Principal Compliance Engineer

A handwritten signature in black ink that reads "Andrew Wingerter". The signature is written in a cursive, flowing style.

www.dyson.com

Dyson Technology Limited
REG. IN ENGLAND NO. 01959090
REG. OFFICE: TETBURY HILL, MALMESBURY, WILTSHIRE, SN16 0RP