

寄件者: wendy@adt.com.tw
寄件日期: 2005年1月17日星期一 下午 8:08
收件者: steve.cheng@nacsemc.com
副本: stephanie@adt.com.tw
主旨: Solve the comment for (Sonicwall FCC ID: QWU-03A)

Dear Steve

Question #1: P6 of test report stated two modes are identical, but internal photos shown different RF module was use in two models. Please clarify.

Answer:

1. We only tested the mini PCI card which model is WL-850F, so remove the page 7 that Mini PCI card which model is

XG-601 in the test report.

2. We also remove Mini PCI card which model is XG-601 in the external and internal photos.

Please check

Thanks for your asistance!

Best Regards
Wendy Liao

Wendy Liao (廖意紋)/ ADT Corp.
TEL: 03-318-3232 EXT 1625
FAX: 03-318-5050
Email: wendy@adt.com.tw
地址: 桃園縣龜山鄉文化村華亞二路 1 9 號