

Response to E04-000099-1

1. The 731 form should have listed two separate specifications for the 125 kHz and 13.56 MHz parts. Please correct it for me.
2. The equipment code for the 13.56 MHz product should be DXT.
3. Label placement has been uploaded.
4. The customer says the users manual does not mention parts 11, 15 or 18, but the manual has been re-uploaded.