

Response to E04-000091-1 & E04-000091-1 IC

1. The equipment code on the 731 form should be DXT.
2. A revised test report has been uploaded with in-cal equipment.
3. The manufacturer has been changed in the revised test report.