



BABT
Claremont House, 34 Molesey Road
Walton on Thames
Surrey, KT12 4RQ
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Ref: US000088

25 October 2004

To FCC

Direct Dial: +44 (0)1932 251247
E-mail: bill.wilson@babt.com
Website: www.babt.com

**Evaluation of Newgen S510
FCC id: R5WNGTS510T**

I have assessed the submission and find it compliant.

The following were noted and resolved during the evaluation.

- 1: The Part 22, 24 test report contained typing errors which appeared to place one test frequency outside the permitted band. A revised report was supplied.
- 2: Covering letters were not obviously from the applicant and were not addressed to BABT. Replacement letters were provided.
- 3: An incorrect plot was supplied in the test plot file. A revised file was supplied.

Yours sincerely

Bill Wilson
Technical Certifier
For BABT TCB