







Band4-15MHz-64QAM-20025-75RB#0




Band4-15MHz-64QAM-20175-75RB#0




Band4-15MHz-64QAM-20325-75RB#0




Band4-20MHz-QPSK-20050-100RB#0




Band4-20MHz-QPSK-20175-100RB#0




Band4-20MHz-QPSK-20300-100RB#0




Band4-20MHz-16QAM-20050-100RB#0




Band4-20MHz-16QAM-20175-100RB#0




Band4-20MHz-16QAM-20300-100RB#0




Band4-20MHz-64QAM-20050-100RB#0




Band4-20MHz-64QAM-20175-100RB#0



Band4-20MHz-64QAM-20300-100RB#0




Date: 9.AUG.2022 14:06:48




Date: 9.AUG.2022 14:07:06

Band5-1.4MHz-QPSK-20407-6RB#0




Date: 9.AUG.2022 14:07:23




Date: 9.AUG.2022 14:07:41

Band5-1.4MHz-QPSK-20525-6RB#0



Date: 9.AUG.2022 14:07:58



Date: 9.AUG.2022 14:08:16

Band5-1.4MHz-QPSK-20643-6RB#0

Band5-1.4MHz-16QAM-20643-6RB#0



Band5-1.4MHz-64QAM-20407-6RB#0



Band5-3MHz-QPSK-20415-15RB#0



Band5-1.4MHz-64QAM-20525-6RB#0





Band5-3MHz-QPSK-20525-15RB#0





Band5-1.4MHz-64QAM-20643-6RB#0





Band5-3MHz-QPSK-20635-15RB#0





Band5-3MHz-64QAM-20415-15RB#0



Band5-3MHz-64QAM-20525-15RB#0





Band5-3MHz-64QAM-20635-15RB#0





Band5-5MHz-QPSK-20425-25RB#0

Band5-5MHz-16QAM-20425-25RB#0




Band5-5MHz-QPSK-20525-25RB#0

Band5-5MHz-16QAM-20525-25RB#0




Band5-5MHz-QPSK-20625-25RB#0

Band5-5MHz-16QAM-20625-25RB#0




Date: 1.AUG.2022 15:28:50

Band5-5MHz-64QAM-20425-25RB#0




Date: 1.AUG.2022 15:29:15

Band5-5MHz-64QAM-20525-25RB#0




Date: 1.AUG.2022 15:29:39

Band5-5MHz-64QAM-20625-25RB#0




Date: 27.JUL.2022 11:21:22

Band5-10MHz-QPSK-20450-50RB#0




Date: 27.JUL.2022 11:21:58

Band5-10MHz-QPSK-20525-50RB#0




Date: 27.JUL.2022 11:22:33

Band5-10MHz-QPSK-20600-50RB#0




Date: 27.JUL.2022 11:21:40

Band5-10MHz-16QAM-20450-50RB#0




Date: 27.JUL.2022 11:22:15

Band5-10MHz-16QAM-20525-50RB#0




Date: 27.JUL.2022 11:22:50

Band5-10MHz-16QAM-20600-50RB#0




Date: 1.AUG.2022 15:30:35

Band5-10MHz-64QAM-20450-50RB#0




Date: 1.AUG.2022 15:30:53

Band5-10MHz-64QAM-20525-50RB#0




Date: 1.AUG.2022 15:31:11

Band5-10MHz-64QAM-20600-50RB#0




Date: 9.AUG.2022 14:12:01

Band7-5MHz-QPSK-20775-25RB#0




Date: 9.AUG.2022 14:12:26

Band7-5MHz-16QAM-20775-25RB#0




Date: 9.AUG.2022 14:12:50

Band7-5MHz-QPSK-21100-25RB#0




Date: 9.AUG.2022 14:13:15

Band7-5MHz-16QAM-21100-25RB#0





Date: 9.AUG.2022 14:13:40

Band7-5MHz-QPSK-21425-25RB#0





Date: 9.AUG.2022 14:14:04



Band7-5MHz-16QAM-21425-25RB#0









Band7-10MHz-QPSK-20800-50RB#0





Band7-10MHz-QPSK-21100-50RB#0





Band7-10MHz-QPSK-21400-50RB#0













Band7-15MHz-16QAM-20825-75RB#0




Band7-15MHz-16QAM-21100-75RB#0




Band7-15MHz-16QAM-21375-75RB#0






Date: 27.JUL.2022 14:12:35




Date: 1.AUG.2022 15:54:20

Band7-20MHz-16QAM-20850-100RB#0




Date: 27.JUL.2022 14:13:10




Date: 1.AUG.2022 15:54:38

Band7-20MHz-16QAM-21100-100RB#0




Date: 27.JUL.2022 14:13:46




Date: 1.AUG.2022 15:54:56

Band7-20MHz-16QAM-21350-100RB#0

Band7-20MHz-64QAM-21350-100RB#0




Date: 9.AUG.2022 14:05:20




Date: 27.JUL.2022 15:49:54

Band12-1.4MHz-QPSK-23017-6RB#0




Date: 27.JUL.2022 15:50:11




Date: 27.JUL.2022 15:50:29

Band12-1.4MHz-QPSK-23095-6RB#0




Date: 27.JUL.2022 15:50:47



Date: 27.JUL.2022 15:51:04


Band12-1.4MHz-QPSK-23173-6RB#0

Band12-1.4MHz-16QAM-23173-6RB#0




Date: 9.AUG.2022 14:29:07

Band12-1.4MHz-64QAM-23017-6RB#0




Date: 27.JUL.2022 15:51:51

Band12-3MHz-QPSK-23025-15RB#0




Date: 9.AUG.2022 14:29:25

Band12-1.4MHz-64QAM-23095-6RB#0




Date: 27.JUL.2022 15:52:27

Band12-3MHz-QPSK-23095-15RB#0




Date: 9.AUG.2022 14:29:49

Band12-1.4MHz-64QAM-23173-6RB#0




Date: 27.JUL.2022 15:53:02


Band12-3MHz-QPSK-23165-15RB#0




Band12-3MHz-16QAM-23025-15RB#0




Band12-3MHz-16QAM-23095-15RB#0




Band12-3MHz-16QAM-23165-15RB#0




Band12-3MHz-64QAM-23025-15RB#0




Band12-3MHz-64QAM-23095-15RB#0



Band12-3MHz-64QAM-23165-15RB#0




Date: 27.JUL.2022 15:54:13




Date: 27.JUL.2022 15:54:38

Band12-5MHz-QPSK-23035-25RB#0




Date: 27.JUL.2022 15:55:02




Date: 27.JUL.2022 15:55:27

Band12-5MHz-QPSK-23095-25RB#0




Date: 27.JUL.2022 15:55:52




Date: 27.JUL.2022 15:56:16

Band12-5MHz-QPSK-23155-25RB#0


Band12-5MHz-16QAM-23155-25RB#0




Band12-5MHz-64QAM-23035-25RB#0




Band12-5MHz-64QAM-23095-25RB#0




Band12-5MHz-64QAM-23155-25RB#0




Band12-10MHz-QPSK-23060-50RB#0










Band12-10MHz-QPSK-23095-50RB#0




Band12-10MHz-QPSK-23130-50RB#0








Date: 9.AUG.2022 15:40:43




Date: 27.JUL.2022 16:54:06

Band13-5MHz-64QAM-23205-25RB#0

Band13-10MHz-QPSK-23230-50RB#0




Date: 1.AUG.2022 16:46:37




Date: 27.JUL.2022 16:54:24

Band13-5MHz-64QAM-23230-25RB#0

Band13-10MHz-16QAM-23230-50RB#0





Date: 1.AUG.2022 16:47:01




Date: 9.AUG.2022 14:34:30

Band13-5MHz-64QAM-23255-25RB#0


Band13-10MHz-64QAM-23230-50RB#0




Band17-5MHz-QPSK-23755-25RB#0




Band17-5MHz-16QAM-23755-25RB#0



Band17-5MHz-QPSK-23790-25RB#0





Band17-5MHz-16QAM-23790-25RB#0



Band17-5MHz-QPSK-23825-25RB#0


Band17-5MHz-16QAM-23825-25RB#0






Date: 9.AUG.2022 14:09:46

Band17-10MHz-16QAM-23780-50RB#0




Date: 1.AUG.2022 16:55:23

Band17-10MHz-64QAM-23780-50RB#0




Date: 9.AUG.2022 14:10:21

Band17-10MHz-16QAM-23790-50RB#0




Date: 1.AUG.2022 16:55:40

Band17-10MHz-64QAM-23790-50RB#0




Date: 9.AUG.2022 14:10:57

Band17-10MHz-16QAM-23800-50RB#0




Date: 1.AUG.2022 16:55:58

Band17-10MHz-64QAM-23800-50RB#0




Date: 27.JUL.2022 18:30:17

Band26-1.4MHz-QPSK-26697-6RB#0




Date: 27.JUL.2022 18:30:34

Band26-1.4MHz-16QAM-26697-6RB#0




Date: 27.JUL.2022 18:30:52

Band26-1.4MHz-QPSK-26740-6RB#0




Date: 27.JUL.2022 18:31:09

Band26-1.4MHz-16QAM-26740-6RB#0




Date: 27.JUL.2022 18:31:27

Band26-1.4MHz-QPSK-26783-6RB#0




Date: 27.JUL.2022 18:31:45


Band26-1.4MHz-16QAM-26783-6RB#0




Band26-1.4MHz-64QAM-26697-6RB#0




Band26-1.4MHz-64QAM-26740-6RB#0




Band26-1.4MHz-64QAM-26783-6RB#0




Band26-3MHz-QPSK-26705-15RB#0




Band26-3MHz-QPSK-26740-15RB#0




Band26-3MHz-QPSK-26775-15RB#0




Band26-3MHz-16QAM-26705-15RB#0




Band26-3MHz-16QAM-26740-15RB#0




Band26-3MHz-16QAM-26775-15RB#0





Band26-3MHz-64QAM-26705-15RB#0





Band26-3MHz-64QAM-26740-15RB#0





Band26-3MHz-64QAM-26775-15RB#0




Band26-5MHz-16QAM-26715-25RB#0



Band26-5MHz-16QAM-26740-25RB#0




Band26-5MHz-16QAM-26765-25RB#0




Date: 1.AUG.2022 17:05:11

Band26-5MHz-64QAM-26715-25RB#0




Date: 1.AUG.2022 17:05:36

Band26-5MHz-64QAM-26740-25RB#0




Date: 1.AUG.2022 17:06:00

Band26-5MHz-64QAM-26765-25RB#0




Date: 27.JUL.2022 18:38:01

Band26-10MHz-QPSK-26740-50RB#0





Date: 27.JUL.2022 18:38:18

Band26-10MHz-16QAM-26740-50RB#0





Date: 1.AUG.2022 17:07:06

Band26-10MHz-64QAM-26740-50RB#0





Band38-5MHz-QPSK-37775-25RB#0

Band38-5MHz-16QAM-37775-25RB#0




Band38-5MHz-QPSK-38000-25RB#0

Band38-5MHz-16QAM-38000-25RB#0




Band38-5MHz-QPSK-38225-25RB#0

Band38-5MHz-16QAM-38225-25RB#0




Date: 2.AUG.2022 10:02:43

Band38-5MHz-64QAM-37775-25RB#0




Date: 2.AUG.2022 10:03:07

Band38-5MHz-64QAM-38000-25RB#0




Date: 2.AUG.2022 10:03:32


Band38-5MHz-64QAM-38225-25RB#0





Band38-10MHz-QPSK-37800-50RB#0



Band38-10MHz-QPSK-38000-50RB#0




Band38-10MHz-QPSK-38200-50RB#0



Date: 2.AUG.2022 10:04:30

Band38-10MHz-16QAM-37800-50RB#0


Band38-10MHz-64QAM-37800-50RB#0



Date: 2.AUG.2022 10:04:47

Band38-10MHz-16QAM-38000-50RB#0



Band38-10MHz-64QAM-38000-50RB#0



Date: 2.AUG.2022 10:05:05



Band38-10MHz-16QAM-38200-50RB#0

Band38-10MHz-64QAM-38200-50RB#0





Band38-15MHz-QPSK-37825-75RB#0

Band38-15MHz-16QAM-37825-75RB#0




Band38-15MHz-QPSK-38000-75RB#0

Band38-15MHz-16QAM-38000-75RB#0




Band38-15MHz-QPSK-38175-75RB#0

Band38-15MHz-16QAM-38175-75RB#0




Date: 2.AUG.2022 10:06:01

Band38-15MHz-64QAM-37825-75RB#0




Date: 2.AUG.2022 10:06:18

Band38-15MHz-64QAM-38000-75RB#0




Date: 2.AUG.2022 10:06:36


Band38-15MHz-64QAM-38175-75RB#0





Band38-20MHz-QPSK-37850-100RB#0



Band38-20MHz-QPSK-38000-100RB#0





Band38-20MHz-QPSK-38150-100RB#0





Band38-20MHz-16QAM-37850-100RB#0

Band38-20MHz-64QAM-37850-100RB#0





Band38-20MHz-16QAM-38000-100RB#0

Band38-20MHz-64QAM-38000-100RB#0





Band38-20MHz-16QAM-38150-100RB#0



Band38-20MHz-64QAM-38150-100RB#0



Band41-5MHz-16QAM-40065-25RB#0



Band41-5MHz-16QAM-40590-25RB#0



Band41-5MHz-16QAM-41215-25RB#0

