







Band5-1.4MHz-QPSK-20407-1RB#0




Band5-1.4MHz-QPSK-20643-6RB#0




Band5-1.4MHz-QPSK-20407-6RB#0




Band5-1.4MHz-16QAM-20407-1RB#0




Band5-1.4MHz-QPSK-20643-1RB#5



Band5-1.4MHz-16QAM-20407-6RB#0




Band5-1.4MHz-16QAM-20643-1RB#5




Band5-1.4MHz-64QAM-20407-6RB#0




Band5-1.4MHz-16QAM-20643-6RB#0




Band5-1.4MHz-64QAM-20643-1RB#5




Band5-1.4MHz-64QAM-20407-1RB#0




Band5-1.4MHz-64QAM-20643-6RB#0






Band5-3MHz-16QAM-20635-1RB#14




Band5-3MHz-64QAM-20415-15RB#0



Band5-3MHz-16QAM-20635-15RB#0




Band5-3MHz-64QAM-20635-1RB#14




Band5-3MHz-64QAM-20415-1RB#0




Band5-3MHz-64QAM-20635-15RB#0






Band5-5MHz-16QAM-20625-1RB#24




Band5-5MHz-64QAM-20425-25RB#0




Band5-5MHz-16QAM-20625-25RB#0




Band5-5MHz-64QAM-20625-1RB#24



Band5-5MHz-64QAM-20425-1RB#0




Band5-5MHz-64QAM-20625-25RB#0





Band5-10MHz-16QAM-20600-1RB#49




Band5-10MHz-64QAM-20450-50RB#0



Band5-10MHz-16QAM-20600-50RB#0




Band5-10MHz-64QAM-20600-1RB#49



Band5-10MHz-64QAM-20450-1RB#0




Band5-10MHz-64QAM-20600-50RB#0




Date: 27.JUL.2022 15:05:47

Band7-5MHz-QPSK-20775-1RB#0




Date: 27.JUL.2022 14:52:20

Band7-5MHz-QPSK-21425-25RB#0




Date: 27.JUL.2022 15:06:29

Band7-5MHz-QPSK-20775-25RB#0




Date: 27.JUL.2022 15:06:08

Band7-5MHz-16QAM-20775-1RB#0




Date: 27.JUL.2022 14:51:38

Band7-5MHz-QPSK-21425-1RB#24




Date: 27.JUL.2022 15:06:50


Band7-5MHz-16QAM-20775-25RB#0




Band7-5MHz-16QAM-21425-1RB#24




Band7-5MHz-64QAM-20775-25RB#0




Band7-5MHz-16QAM-21425-25RB#0




Band7-5MHz-64QAM-21425-1RB#24



Band7-5MHz-64QAM-20775-1RB#0




Band7-5MHz-64QAM-21425-25RB#0




Date: 27.JUL.2022 15:03:45

### Band7-10MHz-QPSK-20800-1RB#0




Date: 27.JUL.2022 14:54:32

### Band7-10MHz-QPSK-21400-50RB#0




Date: 27.JUL.2022 15:04:27

### Band7-10MHz-QPSK-20800-50RB#0




Date: 27.JUL.2022 15:04:06

### Band7-10MHz-16QAM-20800-1RB#0




Date: 27.JUL.2022 14:53:50

### Band7-10MHz-QPSK-21400-1RB#49




Date: 27.JUL.2022 15:04:48

### Band7-10MHz-16QAM-20800-50RB#0




Date: 27.JUL.2022 14:54:11

### Band7-10MHz-16QAM-21400-1RB#49




Date: 2.AUG.2022 09:31:06

### Band7-10MHz-64QAM-20800-50RB#0




Date: 27.JUL.2022 14:54:53

### Band7-10MHz-16QAM-21400-50RB#0




Date: 2.AUG.2022 09:22:50

### Band7-10MHz-64QAM-21400-1RB#49




Date: 2.AUG.2022 09:30:45

### Band7-10MHz-64QAM-20800-1RB#0




Date: 2.AUG.2022 09:23:11

### Band7-10MHz-64QAM-21400-50RB#0




Date: 27.JUL.2022 15:01:35

Band7-15MHz-QPSK-20825-1RB#0




Date: 27.JUL.2022 14:56:28

Band7-15MHz-QPSK-21375-75RB#0




Date: 27.JUL.2022 15:02:17

Band7-15MHz-QPSK-20825-75RB#0




Date: 27.JUL.2022 15:01:56

Band7-15MHz-16QAM-20825-1RB#0




Date: 27.JUL.2022 14:55:47

Band7-15MHz-QPSK-21375-1RB#74




Date: 27.JUL.2022 15:02:37

Band7-15MHz-16QAM-20825-75RB#0




Date: 27.JUL.2022 14:56:07

### Band7-15MHz-16QAM-21375-1RB#74




Date: 2.AUG.2022 09:29:24

### Band7-15MHz-64QAM-20825-75RB#0




Date: 27.JUL.2022 14:56:49

### Band7-15MHz-16QAM-21375-75RB#0




Date: 2.AUG.2022 09:24:31

### Band7-15MHz-64QAM-21375-1RB#74




Date: 25.AUG.2022 08:57:58

### Band7-15MHz-64QAM-20825-1RB#0



Date: 2.AUG.2022 09:24:52


### Band7-15MHz-64QAM-21375-75RB#0



Band7-20MHz-QPSK-20850-1RB#0




Band7-20MHz-QPSK-21350-100RB#0




Date: 27.JUL.2022 15:00:20


Band7-20MHz-QPSK-20850-100RB#0




Band7-20MHz-16QAM-20850-1RB#0




Band7-20MHz-QPSK-21350-1RB#99




Band7-20MHz-16QAM-20850-100RB#0



Band7-20MHz-16QAM-21350-1RB#99




Band7-20MHz-64QAM-20850-100RB#0




Date: 27.JUL.2022 14:58:45


Band7-20MHz-16QAM-21350-100RB#0



Band7-20MHz-64QAM-21350-1RB#99




Band7-20MHz-64QAM-20850-1RB#0




Date: 2.AUG.2022 09:26:16


Band7-20MHz-64QAM-21350-100RB#0




Band12-1.4MHz-QPSK-23017-1RB#0




Band12-1.4MHz-QPSK-23173-6RB#0




Band12-1.4MHz-QPSK-23017-6RB#0



Band12-1.4MHz-16QAM-23017-1RB#0



Band12-1.4MHz-QPSK-23173-1RB#5



Band12-1.4MHz-16QAM-23017-6RB#0

