



3. Internal Photograph of EUT

Model Name: 3022D, 3022G


Single SIM slot




Model Name: 3022D, 3022G



Model Name: 3022D, 3022G



Model Name: 3022D, 3022G






Model Name: 3022D, 3022G






Model Name: 3022D, 3022G







Model Name: 3022D, 3022G




Model Name: 3022D, 3022G




Model Name: 3022D, 3022G




Model Name: 3022D, 3022G




Model Name: 3022D, 3022G






Model Name: 3022D, 3022G






Model Name: 3022D, 3022G




Model Name: 3022D, 3022G




Model Name: 3022D, 3022G



Model Name: 3022D, 3022G



Model Name: 3022D, 3022G






Model Name: 3022D, 3022G



Model Name: 3022D, 3022G






Model Name: 3022D, 3022G






Model Name: 3022D, 3022G






Model Name: 3022D, 3022G







Model Name: 3022D, 3022G



Page Number : 35 of 44
Report Issued Date : Sep. 12, 2014
Report Version : Rev. 01


Model Name: 3022D, 3022G









Model Name: 3022D, 3022G




Model Name: 3022D, 3022G



Model Name: 3022D, 3022G




Model Name: 3022D, 3022G






Model Name: 3022D, 3022G





Model Name: 3022D, 3022G



Model Name: 3022D, 3022G

