

FCC ID Label Format and Location

- Label Placement Location (Back Side of EUT)

M/N: TSK-M3204ME



M/N: TSK-M3204MEQ



FCC Label Placement Location

- FCC Label Format

	HOUSEHOLD MICROWAVE OVEN	
MODEL NO. : TSK-M3204ME MANUFACTURED : July 2006		49DT E237415
Serial Number		
INPUT 120 V AC, 15 A, 60 Hz OUTPUT 2450 MHz		
DISTRIBUTED BY: Tsann Kuen Industrial Park, Longchi Development District, Zhangzhou, Fujian 363000, China		
THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J.		
FCC ID:		MADE IN CHINA (TKL)
NOT FOR BUILT-IN INSTALLATION		
WARNING – CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL – DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, TURNABLE MOTOR, OR LOW VOLTAGE TRANSFORMER.		
WARNING – RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.		
WARNING – TO PROVIDE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.		
CAUTION – THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.		

	HOUSEHOLD MICROWAVE OVEN	
MODEL NO. : TSK-M3204MEQ MANUFACTURED : July 2006		49DT E237415
Serial Number		
INPUT 120 V AC, 15 A, 60 Hz OUTPUT 2450 MHz		
DISTRIBUTED BY: Tsann Kuen Industrial Park, Longchi Development District, Zhangzhou, Fujian 363000, China		
THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J.		
FCC ID:		MADE IN CHINA (TKL)
NOT FOR BUILT-IN INSTALLATION		
WARNING – CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL – DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, TURNABLE MOTOR, OR LOW VOLTAGE TRANSFORMER.		
WARNING – RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.		
WARNING – TO PROVIDE CONTINUED PROTECTION AGAINST ELECTRIC SHOCK, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.		
CAUTION – THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.		