

Contacts and Important Information

Customer Care

1-800-591-3455 (24 hours/7 days)

From Outside the US: 1-978-600-7850

Customer Care Fax: 877-467-8538

Address: Insulet Corporation
100 Nagog Park, Acton MA 01720

Emergency Services: Dial 911 (USA only; not available in all communities)

Website: omnipod.com

Controller Model: PDM-USA-H001-MG

Serial Number: _____

Controller FCC ID: 2ADINN5004L

Pod FCC ID: RBV-029

Omnipod® 5 Automated Insulin Delivery System

Start Date: _____

Healthcare Provider

Name

Street Address

City State Zip

Phone

Email

Omnipod® Trainer

Name

Street Address

City State Zip

Phone

Email

Health Insurance

Name

Street Address

City State Zip

Phone

Policy Number

Pharmacy

Name

Street Address

City State Zip

Phone

Email

Symbol	Meaning	Symbol	Meaning		
IP22	Protects persons against access to hazardous parts with fingers and protects against solid foreign object ingress of diameter 12.5 mm or greater; avoid liquid	Rx ONLY	Prescription only		
	Do not dispose with household waste	RoHS	RoHS compliant		
CE	Marking of conformity	<table border="1"><tr><td>EC</td><td>REP</td></tr></table>	EC	REP	Representative in the European Community
EC	REP				

Omnipod 5 System Notice Concerning Interference

Caution: DO NOT make changes or modifications to any component of the Omnipod 5 System that has not been authorized by Insulet Corporation. Unauthorized tampering with the System can revoke your right to operate it.


 is equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy, and, if not installed and used in accordance with the instructions may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If the equipment does cause harmful interference to radio and television reception, the user is encouraged to try to correct the interference by one of the following measures:

- Move or relocate the Omnipod 5 System.
- Increase the separation between the Omnipod 5 System and the other device that is emitting or receiving interference.
- Consult the dealer or an experienced radio/TV technician for help.



Insulet Corporation
100 Nagog Park
Acton, MA 01720
1-800-591-3455 | 1-978-600-7850
omnipod.com



Pod shown without the necessary adhesive.



FCC ID: 2ADINN5004L
Controller

FCC ID: RBV-0000
P

