

Circuit Description

Switching on the power controller, sensor and MCU can get the power to be stand by. Set up ID code via SW6, and then input an electric signal into the MCU to have the data process. MCU will output a relevant signal to make the optical sensors and keys working after data processed.

Please reset the ID code via SW6 after changed the batteries