

Label of Model: 28559


Fan Accessory Damp Location Light Kit		Vendor No.: 219030
120 VAC, 60Hz, 42W	Model: 28559 SKU#XXX-XXX	FCC ID: RGB-ADBLK2855X
UPC#082392285593		Made in China
Conforms To UL STD. 1598		03/14
Certified To CSA STD. C22.2 No. 250.0		
2x Max. Spiral Type 14W CFL bulb		

CAUTION To reduce the risk of fire and electric shock,
install light kit only on ceiling fan models
specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to
the following two conditions: (1) this device may not cause harmful interference,
and (2) this device must accept any interference received, including interference
that may cause undesired operation.

FCC **ETL** **us**
C LISTED
Intertek
3160823

80x55mm



Label of Model: 28556

Fan Accessory Damp Location Light Kit
120 VAC, 60Hz, 42W Model: 28556 SKU#XXX-XXX UPC#08239228556
Conforms To UL STD. 1598 Certified To CSA STD. C22.2 No. 250.0
2x Max. Spiral Type 14W CFL bulb

Vendor No.: 11688
FCC ID: RGB-ADBTLK2855X
Made in China
03/14

CAUTION To reduce the risk of fire and electric shock,
install light kit only on ceiling fan models
specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to
the following two conditions: (1) this device may not cause harmful interference,
and (2) this device must accept any interference received, including interference
that may cause undesired operation.

FCC

ETL

LISTED

US

Intertek
3160823

Label of Model: 28557

Fan Accessory Damp Location Light Kit
120 VAC, 60Hz, 42W Model: 28557 SKU#XXX-XXX UPC#08239228557
Conforms To UL STD. 1598 Certified To CSA STD. C22.2 No. 250.0
2x Max. Spiral Type 14W CFL bulb

Vendor No.: 219030
FCC ID: RGB-ADBTLK2855X
Made in China
03/14

CAUTION To reduce the risk of fire and electric shock,
install light kit only on ceiling fan models
specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to
the following two conditions: (1) this device may not cause harmful interference,
and (2) this device must accept any interference received, including interference
that may cause undesired operation.

FCC

ETL

LISTED

US

Intertek
3160823

Label of Model: 28558

Fan Accessory Damp Location Light Kit
120 VAC, 60Hz, 42W Model: 28558 SKU#XXX-XXX UPC#08239228558
Conforms To UL STD. 1598 Certified To CSA STD. C22.2 No. 250.0
2x Max. Spiral Type 14W CFL bulb

Vendor No.: 219030
FCC ID: RGB-ADBTLK2855X
Made in China
03/14

CAUTION To reduce the risk of fire and electric shock,
install light kit only on ceiling fan models
specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to
the following two conditions: (1) this device may not cause harmful interference,
and (2) this device must accept any interference received, including interference
that may cause undesired operation.

FCC

ETL

LISTED

US

Intertek
3160823