



APPENDIX B. Test Pattern**1.1. 6dB Bandwidth**


Plot1(Channel 1) :



Plot2(Channel 6) :



Plot3(Channel 11) :




Date: 15.OCT.2003 10:03:54


Comments : 6dB Emission bandwidth>500kHz

1.2. Peak Output Power

Plot1(Channel 1):




Plot2(Channel 6):




Date: 15.OCT.2003 10:02:22

Plot3(Channel 11):




1.3. Band Edges Measurement

Plot1 (Channel 1) :



Plot2 (Channel 11) :




Date: 15.OCT.2003 10:07:45


Comments : All emissions in any 100kHz bandwidth outside the band edge are attenuated more than 20dB from the carrier.

1.4. Test of Radiated Emission


(Channel 1):




Date: 9.SEP.2003 15:09:18




Date: 9.SEP.2003 15:11:49




Date: 9.SEP.2003 15:16:26




Date: 9.SEP.2003 15:18:16




Date: 9.SEP.2003 15:19:50




Date: 9.SEP.2003 15:20:43






Date: 9.SEP.2003 15:23:47




Date: 9.SEP.2003 15:24:34




Date: 9.SEP.2003 15:25:34


Channel 6:




Date: 9.SEP.2003 15:44:10




Date: 9.SEP.2003 15:45:35



Date: 9.SEP.2003 15:46:32




Date: 9.SEP.2003 15:47:33



Date: 9.SEP.2003 15:50:03

FCC TEST REPORT

Report No. : F370902



Date: 9.SEP.2003 15:50:59

SPORTON International Inc.


TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC ID. : RC6AMW-734CU


Page No. : B24 of B38

Issued Date : Oct. 16, 2003







Date: 9.SEP.2003 15:52:36



Date: 9.SEP.2003 15:53:16




Channel 11:



Date: 9.SEP.2003 15:27:45

FCC TEST REPORT

Report No. : F370902



Date: 9.SEP.2003 15:29:24

SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC ID. : RC6AMW-734CU

Page No. : B30 of B38

Issued Date : Oct. 16, 2003




Date: 9.SEP.2003 15:30:43



Date: 9.SEP.2003 15:34:16

FCC TEST REPORT

Report No. : F370902



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC ID. : RC6AMW-734CU

Page No. : B33 of B38


Issued Date : Oct. 16, 2003




Date: 9.SEP.2003 15:38:41




Date: 9.SEP.2003 15:39:36



Date: 9.SEP.2003 15:40:35



Date: 9.SEP.2003 15:41:36



Date: 9.SEP.2003 15:42:19