



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 22, 2003

RE: Lasershield Systems, Inc.

FCC ID: RIHK0011500

After a review of the submitted information, I have a few comments on the above referenced Application.

General

- 1) Please provide pages 5 & 6 of the R53085-cover letters as a separate exhibit to be uploaded to the FCC site.
- 2) The FCC ID and Identifier must be located on a single line as given in 2.925(a)(1). The FCC ID shown in the label and test report (1 & 4 of 15, 2 of 7), does not match the application 731 form (RIHK0011500 vs. RIHK001150). Please confirm the correct FCC ID and update the label and/or affected exhibits as necessary. Additionally, the drawing showing placement of the label does not look like the device in this application. Please provide an updated photograph or drawing showing the placement of the label.
- 3) Page 4 of 15 states that the device does have predetermined transmissions, which are not allowed. Please explain.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.