

# INTERTEK TESTING SERVICES

Report No.: 040561  
Model No.: JW-404

hp

Pursuant to FCC Part 15 Section 15.223 Emissions Requirement MKR 16.688 msec


REF -10.0 dBm

AT 10 dB

.03 dB

PEAK  
LOG  
10  
dB/

WA SB  
SC LS  
CORR



Tested By:

Date: 13-4-04

Checked By:

Date: 16/4/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

hp

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKR 16.650 msec

Report No.: 0405671

Model No.: N-404


REF -10.0 dBm

AT 10 dB

-.02 dB

PEAK  
LOG  
10  
dB/

WA SB  
SC LS  
CORR



Tested By: *[Signature]*  
(Banyo)

Date: 13-4-04

Checked By: *[Signature]*  
(Van)

Date: 16/4/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0405671  
Model No.: N-404

hp

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement MKR 1.3500 msec


REF -10.0 dBm

AT 10 dB

.05 dB

PEAK  
LOG  
10  
dB/

WA SB  
SC LS  
CORR



Tested By:

Date: 13-4-04

Checked By:

Date: 16/4/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

# INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15.227 Emissions Requirements

MKR 450.00  $\mu$ sec

Report No.: 0405671

Model No.: W-404


REF -10.0 dBm

AT 10 dB

.02 dB

PEAK  
LOG  
10  
dB/

WA SB  
SC LS  
CORR



Tested By:

Date: 13-4-04

Checked By:

Date: 16/4/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec