


Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Four – Internal

Hand Held Spa Controller Open for Inspection




Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Five – Internal

**Hand Held Spa Controller Open for Inspection
Key Board Contacts**




Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Six – Internal

**Hand Held Spa Controller Open for Inspection
Key Board PCB Close Up**




Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Seven – Internal

**Hand Held Spa Controller Open for Inspection
Key Board PCB RF Section Close Up**




Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Eight – Internal

**Hand Held Spa Controller Open for Inspection
Key Board PCB Flip Side**




Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Nine – Internal

**Hand Held Spa Controller Open for Inspection
Key Board PCB Flip Side RF Section Close Up**



Goldline Controls Incorporated

**AquaLogic Spa-side Remote Control
902 – 926 MHz Radio**

FCC ID#: RNW-AQLSPASIDE-RF

Photo Ten – Internal

**Hand Held Spa Controller Open for Inspection
Key Board PCB Flip Side RF Section Close Up
with PCB Antenna**

