
INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031435HKG-001

Equipment Photographs

Model : HF-638PBT

(Internal)

