


INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs


Model: JTA-455

(Internal)



Report No.: 15060062HKG-001

Model: JTA-455




INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)




INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15060062HKG-001

Equipment Photographs

Model: JTA-455

(Internal)

