

# INTERTEK TESTING SERVICE

Report No.: 17061279HKG-001

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

## Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

### Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 17061279HKG-001

## Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

### Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

### Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: 17061279HKG-001

### Equipment Photographs

(Internal)



## INTERTEK TESTING SERVICE

Report No.: 17061279HKG-001

### Equipment Photographs

(Internal)

