

Tim,

Thank you for your comments on this project.

The applicant would like to modify their FCC ID from RRSBTHF009 to **RRSHF009**.

We've made changes to all those documents need to be modified.

Please find attached files for this application. (I've also upload these files to ATCB website.)

Answers to your comments:

1. Please see "Internal Photo (ver.02)".
2. Please see "FCC ID Label (ver.02)".
3. Please see " BTR110_spec[1]" for the information of module manufacture.
4. The extensive modification was made for ESD part of CE testing. So we remove the modification and test again to make sure the Radiated Emission meets FCC limits.
5. Point 2391.0 on page 33 is a typing error. It is the fundamental. We omitted that point.
6. Both lying down and standing up position were tested. We added a narrative on page 10. Please refer to page 10 for this issue.

Elisa Chen

E&E Lab. of SGS Taiwan Ltd.

E-Mail: elisa.chen@sgs.com

TEL: +886 2 2299 3279 ext. 1161

FAX: +886 2 2298 2698

No. 134, Wu Kung Road, Wuku Industrial Zone,

