



Sirius XM Radio Inc.
1500 Eckington Place NE
Washington, DC 20002

T: 202-380-4000
F: 202-380-4500

Washington DC November 30, 2015

To Whom It May Concern:

Tuning Procedure for the TLB Low Power Transmitter (FCC ID: RS2TLB002W)

This is to affirm that a tuning procedure for the TLB Low Power Transmitter (Low Band) is not required as the signal outputs are at a fixed frequency and bandwidth. As such, no tuning procedure has been submitted as part of this FCC application.

Regards,

A handwritten signature in black ink, appearing to read "Beejay Jolayemi", written over a horizontal line.

Beejay Jolayemi

Sr. Technical Staff – Repeater Engineering and Operations
FCC & Industry Canada Compliance



1500 Eckington Place, NE
Washington, DC 20002
Phone: (202)-459-2526
Mobile: (202)-680-4288
Fax: (202)-380-4091
beejay.jolayemi@siriusxm.com