

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083

IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)





FCC ID: RS4-B6083
IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083



IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)





FCC ID: RS4-B6083
IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083

IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)





FCC ID: RS4-B6083
IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083


IC: 4502A-CAB6083

INTERTEK TESTING SERVICE

Report No.: 16040840HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083

IC: 4502A-CAB6083