

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A


IC: 4502A-CAB6083A

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A



IC: 4502A-CAB6083A

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A



IC: 4502A-CAB6083A

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A

IC: 4502A-CAB6083A

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A



IC: 4502A-CAB6083A

INTERTEK TESTING SERVICE

Report No.: 16051991HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6083A

IC: 4502A-CAB6083A