

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572



IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572

IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)




FCC ID: RS4-B6572
IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)





FCC ID: RS4-B6572
IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572

IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572


IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572

IC: 4502A-CAB6572

INTERTEK TESTING SERVICE

Report No.: 16011110HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B6572

IC: 4502A-CAB6572