


INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)



FCC ID: RS4-B7076

IC: 4502A-B7076

INTERTEK TESTING SERVICE

Report No.: 16081048HKG-001

Equipment Photographs

(Internal)

