

INTERTEK TESTING SERVICE

Report No.: 15040307HKG-001

Equipment Photographs

Model: B1075

(External)

