

Cellphone-Mate Inc. dba SureCall

Mar 11, 2025

Subject: Tuning and Adjustment of Signal booster, FCC ID: RSN-FUSION5G

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Dennis Findley

A handwritten signature in black ink that reads "Dennis Findley". The script is cursive and fluid, with the first name "Dennis" and last name "Findley" clearly legible.