

SAR test process

- PCS1900 band SAR test process

1. Insert the SIM card
2. Check of PCS1900 band selection (CMU200, E5515C)
3. Turn on the Hermes Tri radio
4. Try to call from E5515C or CMU200
5. Change of SAR test channel
6. Measured SAR