







PRINT/DOW
0-03-03 MO

GND VRF TXD TXS GND ANT
J1
C4
C2 C1 C3 R2 R8 R9 C16
C12
C13
C9
C7
C5
C6
C8
Y1
U1
R3
R4
R5
R6
R7
R10
R11
R12
Phantom II 14
Ironbros200308A
COMP

P1

S1

Y34

D2

J2