



INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175



(Internal)



Equipment Photographs

Model : WHP-175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175



(Internal)



Equipment Photographs

Model : WHP-175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175

(Internal)




INTERTEK TESTING SERVICE

Report no.: 04058791

Equipment Photographs

Model : WHP-175

(Internal)



Equipment Photographs

Model : WHP-175

(Internal)

