



INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175



(Internal)



Equipment Photographs

Model : WHP - 175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175



(Internal)



Equipment Photographs

Model : WHP - 175

(Internal)





INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175

(Internal)




INTERTEK TESTING SERVICE

Report no.: 04058792

Equipment Photographs

Model : WHP - 175

(Internal)



Equipment Photographs

Model : WHP - 175

(Internal)

