



PCTC
Product Compliance Test Center
2476 Swedesford Road, Malvern, PA 19355

September 15, 2006

David Waitt
American Telecommunications Certification Body, Inc.
6731 Whittier Avenue
McLean, VA 22101

Reference: Identification Change for RF Modules

Dear Mr. Waitt,

The Unisys Product Compliance Test Center (PCTC) would like to submit the request for change of FCC and IC identifications on behalf of the Two Technologies, Inc, as below:

RF Module	Original ID	Change ID
2.4 – 2.483 GHZ RF Module (Socket Model: Go WI-FI! P500)	Manufacturer: Socket Communication, Inc. FCC ID: LUB-80211gCF IC ID: 2529A-80211gCF	Change Requester: Two Technologies, Inc. FCC ID: RYJJETTXL2A IC ID: 6103A - JETTXL2A
902 - 928 MHZ RF Module (MaxStream Model: XT09)	Manufacturer: MaxStream, Inc. FCC ID: OUR-9XTEND IC ID: 4214A-9XTEND	Change Requester: Two Technologies, Inc. FCC ID: RYJJETTXL2B IC ID: 6103A - JETTXL2B

Please let me know me if you have any questions, at (610) 648-3758 or via Email at dipak.patel@unisys.com .

Thank you very much.

Very truly yours,

Dipak Patel, Technical Staff Engineer
Unisys PCTC