

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

Radiated Spurious Emission




Photo 1




Photo 2


Worst Case Position

(Horizontal: X-axis / Vertical: Z-axis)




X-axis



Y-axis



Z-axis



*Use the motherboard with no metal plate, therefore this motherboard does not affect the module test condition.

End of Report

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone : +81 478 88 6500

Facsimile : +81 478 82 3373