

From: Michael Heckrotte
Sent: Monday, April 18, 2005 4:45 PM
To: 'weili3@aol.com'
Subject: FW: Shyam Telecom Inc., FCC ID: S3CIRD55FB-30-70, Assessment
NO.: AN05T4695, Notice#2

-----Original Message-----

From: Compliance Certification Services [mailto:mheckrotte@ccsemc.com]
Sent: Monday, April 18, 2005 4:40 PM
To: Michael Heckrotte
Subject: Shyam Telecom Inc., FCC ID: S3CIRD55FB-30-70, Assessment NO.:
AN05T4695, Notice#2

20. The user manual shows a PCS block of 1878 to 1883 MHz paired with 1958 to 1963 MHz, however this block pair is not shown in FCC Rule Part 24.229. Please explain.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.