



Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 1 von 40
Page 1 of 40



MES TUV270505A03.PK
LIM FCC P15.249




MES TUV270505A04.PK
LIM FCC P15.249

A


Prüfbericht - Nr.:
Test Report No.

14007815 003


Seite 3 von 40
Page 3 of 40



MES TUV270505A01.PK
LIM FCC P15.249




MES TUV270505A02.PK
LIM FCC P15.249




Date: 27.MAY.2005 19:17:41

V

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 6 von 40
Page 6 of 40

Date: 27.MAY.2005 19:17:01

✓




Date: 27.MAY.2005 19:22:41

✓

Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 8 von 40
Page 8 of 40




Date: 27.MAY.2005 19:22:59

✓

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 9 von 40
Page 9 of 40



Date: 27.MAY.2005 19:26:24

V

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 10 von 40
Page 10 of 40


Date: 27.MAY.2005 19:26:55

✓

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 11 von 40
Page 11 of 40



Date: 22.APR.2005 19:34:05

V




Date: 22.APR.2005 19:34:37

V

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 13 von 40
Page 13 of 40



Date: 22.APR.2005 19:40:11

V




Date: 22.APR.2005 19:42:48

✓

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 15 von 40
Page 15 of 40




Date: 22.APR.2005 19:45:40

V

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 16 von 40
Page 16 of 40


Date: 22.APR.2005 19:46:07

V

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 17 von 40
Page 17 of 40


Date: 22.APR.2005 19:50:02

V



Date: 22.APR.2005 19:50:22

✓

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 19 von 40
Page 19 of 40


Date: 22.APR.2005 19:53:47

✓

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 20 von 40
Page 20 of 40




Date: 22.APR.2005 19:54:07

✓



Date: 22.APR.2005 19:56:54

✓




Date: 22.APR.2005 19:57:45

V

Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 23 von 40
Page 23 of 40




Date: 27.MAY.2005 19:35:06

H

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 24 von 40
Page 24 of 40




Date: 27.MAY.2005 19:35:25

H




Date: 27.MAY.2005 19:37:41

H




Date: 27.MAY.2005 19:37:59

t)




Date: 27.MAY.2005 19:41:15

14




Date: 27.MAY.2005 19:41:34

(H)



Date: 22.APR.2005 20:20:34

11

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 30 von 40
Page 30 of 40


Date: 22.APR.2005 20:22:10

H

Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 31 von 40
Page 31 of 40




Date: 22.APR.2005 20:27:17

H

Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 32 von 40
Page 32 of 40



Date: 22.APR.2005 20:27:57


H

Prüfbericht - Nr.:
Test Report No.

14007815 003

Seite 33 von 40

Page 33 of 40




Date: 22.APR.2005 20:31:42

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 34 von 40
Page 34 of 40




Date: 22.APR.2005 20:32:20

H

Prüfbericht - Nr.:
Test Report No.**14007815 003**Seite 35 von 40
Page 35 of 40


Date: 22.APR.2005 20:35:15

H



Date: 22.APR.2005 20:35:36

H




Date: 22.APR.2005 20:39:14

11

Prüfbericht - Nr.:
Test Report No.


14007815 003

Seite 38 von 40
Page 38 of 40




Date: 22.APR.2005 20:39:32

H



Date: 22.APR.2005 20:43:26

H



Date: 22.APR.2005 20:44:04

14