


8THS

To read length in centimeters, omit the final zero after the index line. To read length in millimeters, include the final zero.

LINEAR METRIC UNITS AND SYMBOLS
1000 millimeters (mm) = 1 meter (m)

100 centimeters (cm) = 1 meter (m)
1000 meters (m) = 1 kilometer (km)

CONVERSION
inches x 25.4 = millimeters
inches x 2.54 = centimeters
feet x 30.48 = centimeters





RESET

PoE

12VDC



PWR





