



SBW-242B
DVD-ROM/CD-RW DRIVE
5V ⎓
AVOID DIRECT EXPOSURE TO BEAM.
THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS :
(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION. THIS PRODUCT COMPLIES WITH FDA RADIATION PERFORMANCE STANDARDS, 21 CFR CHAPTER 1, SUBCHAPTER J.
THIS CLASS B DIGITAL APPARATUS MEETS ALL REQUIREMENTS OF THE CANADIAN INTERFERENCE-CAUSING EQUIPMENT REGULATIONS.
CET APPAREIL NUMÉRIQUE DE LA CLASSE B RESPECTE TOUTES LES EXIGENCES DU RÉGLEMENT SUR LE MATÉRIEL BROUILLEUR DU CANADA.
Tested To Comply With FCC Standards
FOR HOME OR OFFICE USE
D43014
E204940
CLASS I LASER PRODUCT
DANGER CLASS 3B VISIBLE AND INVISIBLE LASER RADIATION WHEN OPEN AND INTERLOCK DEFEATED. AVOID DIRECT EXPOSURE TO BEAM.
VORSICHT KLASSE 3B SICHTBARE UND UNSICHTBARE LASERSTRAHLUNG WENN ABDECKUNG GEÖFFNET. NICHT DEN STRAHL AUSSETZEN.
ADVARSEL KLASSE 3B SYNLIG OG USYNLIG LASERSTRÅLING NÅR DEKSEL ÅPENS. UNNGÅ EKSPONERING FOR STRÅLEN.
ADVARSEL KLASSE 3B SYNLIG OG USYNLIG LASERSTRÅLING VED ÅBNING. SE IKKE IND I STRÅLEN.
VARNING KLASS 3B SYNLIG OCH OSYNLIG LASERSTRÅLNING NÄR DENNA DEL ÄR ÖPPNAD. STRÅLE ÄR FARLIG.
VARO ! KURSSI 3B NÄKYVÄÄ JA NÄKYMÄTÖN AVATTAESSA OLET ALTTIINA LASERSÄTEILYLLE. ÄLÄ TUIJOTA SÄTEESEEN.
MADE IN CHINA
Factory:C2
CLASS 1 LASER PRODUCT
CLASS 1 LASER PRODUCT TO IEC 60825-1
APPAREIL A LASER DE CLASSE 1
LASER KLASSE 1
NACH IEC 60825-1
LUOKAN 1 LASERLAITE
PRODUIT LASER CATEGORIE 1
KLASSE 1 LASER APPARAT
*DANGER-Invisible laser radiation when open.
Quanta Storage Inc.
CM-2
323, SEC. 2, NANKAN RD., LUCHU, TAOYUAN HSIEN, TAIWAN
931008L04


931008L04



931008L04



931008L04


931008L04



931008L04
SN200 40703



931008L04
SUNON
Magnetic Levitation System
GB0555AGV1-8A
B406
DC5V 1.3W
Y0424
ZP
CLE
MADE IN TAIWAN



931008L04
00
R11
72
73
74
75
76
77
78
79
80
81


931008L04
00
RJ11
041960
71
72
73
74
75
76
77
78



931008L04
S20B
KK0G550081020
QC
2019
OK
78
77
76
75
74
73
72
71






931008L04



931008L04
Actiontec
MD560LMI-2
US: 6OHM501B200204181
TE-A22/K012-03-0284
A02-0419JP
N51
E212044
B340001
TELEPERMIT
This MD560LMI-2 modem may be connected to the Telecom Network
PTC 211 / 03 / 067
RN = 1
TÜV
Rheinland
Product Safety
BAUART GEPRÜFT
TYPE APPROVED
79
80
81
82
83
84
85



931008L04
0881050001900Q42802182QC
MD560LMI-2
TOBB42307975B
79
80
81
82
83



931008L04
7347B387 SL6N6
RH80535 1400/512
INTEL©'02
79
80
81
82
83
84
85



931008L04
78
79
80
81
82
83
84
85



931008L04



L04



931008L04


931008L04
KTS24.5G1K
SY2
SR236
SR235
SC305
SC304
SR205
SR204
SC311
SR203
R040
SR230
SC298
SC292
SR190
SR229
SR228
SR227


931008L04
KTS14.3G1L
SC217
SC166
SC100
SC99
SC103
SC109
SC158 SR102
SC157 SR101
SC156 SR100
SC155 SR99
SC154 SR98
SC153 SR97
SC152 SR96
SC151 SR95
SC150 SR94
SC149 SR93
SR127
SR126
SR125
SR124
SC229
SR123
SR122
SR121
SC237
SR138
SR137
SR136
SR135
SR134
SC235
SC234
CA332163
0344
952018CF



931008L04
4173BD
SU36
SC37
SC36
SC26
SC35
SC27
SC459
SC34
SC23
SC25
SC458
SY4
SR301
SR300
SD30
SD28
SD27
SR38
SR306
SR296
SR26
SD29
Winbond
W83L950D
2348282O-142
427ABSA



931008L04
KTS25.0G1I


931008L04
KTS12.0G1J
OPEN



931008L04


931008L04





931008L04


931008L04


931008L04
V02108500104 C11 S043033
LEOG730003211 82-228-F02010
48.V0852.001
DARFON


931008L04


931008L04
HSD150PX14
ED1.0
HannStar
HannStar Display Corporation
MADE IN TAIWAN
-A02
Rev:0
E212246
G30002K3C033540