

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = CN	Made in China
XX = MY	Assembled in China with PCBA from Malaysia
XX = MX	Assembled in Mexico



PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = CN	Made in China

NOTE: AC connector must be removed to replace batteries. Press tab to remove AC connector.

Clean annually. See User Guide for more info.

Wi-Fi

YYYY, MMM, DD

Smoke sensitivity : x.xxx +/- x.xxx %/ft CBS

CONFORMS TO

UL STD 217, 9th ed

UL STD 2034, 5th ed

Multi-Criteria Smoke and CO Alarm

38707

DSN: BHSC1714LH000770

ETL US

Intertek

XXXXXX

Model RGCUAR-RW

Combination Photoelectric Smoke/CO Alarm w/ Voice, Wireless Interlink, & Wi-Fi, 120VAC (60Hz, 85mA Max) w/ AA battery backup. Constant exposures to high or low temperatures or high humidity may reduce battery life. **SMOKE ALARM:** 3 Long beeps, repeating. **CO ALARM:** 4 quick beeps, repeating. **STANDBY:** AC power-green LED on. DC only-green LED blinks every 60s. **LOW BATTERY:** Amber LED blinks every 6s with 1 chirp every 60s. **FAULT:** Amber LED blinks 1-4 times with 3 chirps every 60s. **END OF UNIT LIFE:** Amber LED blinks twice with 2 chirps every 60s. **Temp Range:** 40° F (4.4° C) to 100° F (37.8° C). **Humidity Range:** 10 to 95% relative humidity (RH), non-condensing.

Contains FCC ID SAK-ESP2S3 FCC ID: SAK-RGCUARRW

⚠ WARNING: Carbon monoxide (CO) is a colorless, odorless, poisonous gas. You can't taste, see, or smell CO, but it can kill in just minutes. This alarm will sound in a 4-beep pattern if life threatening levels of CO are detected. If the alarm sounds: 1) Immediately evacuate all occupants from the space and go outdoors to fresh air. 2) Call emergency responders (911 or fire department) for help; notify the building or vehicle owner, as necessary.

REPLACE BATTERIES AT LEAST ONCE A YEAR.

⚠ WARNING: **USE ONLY BATTERIES SPECIFIED IN MARKING** (Energizer E91, Gold Peak 15A, Golden Power GLRGAL). **USE OF A DIFFERENT BATTERY MAY HAVE A DETRIMENTAL EFFECT ON ALARM OPERATION.** NOTE: Do not use lithium batteries in this unit.

Unit will not attach to mounting bracket without batteries installed.

Made in China.

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = MY	Assembled in China with PCBA from Malaysia

NOTE: AC connector must be removed to replace batteries. Press tab to remove AC connector.

Clean annually. See User Guide for more info.

Wi-Fi

YYYY, MMM, DD

Smoke sensitivity : x.xx +/- x.xx %/ft OBS



38707

DSN: BHSC1714LH000770

L000351MY00 Rev A

 **US**

Intertek

XXXXXX

Model RGCUAR-RW

Combination Photoelectric Smoke/CO Alarm w/ Voice, Wireless Interlink, & Wi-Fi, 120VAC (60Hz, 85mA Max) w/ AA battery backup. Constant exposures to high or low temperatures or high humidity may reduce battery life. **SMOKE ALARM:** 3 Long beeps, repeating. **CO ALARM:** 4 quick beeps, repeating. **STANDBY:** AC power-green LED on, DC only-green LED blinks every 60s. **LOW BATTERY:** Amber LED blinks every 6s with 1 chirp every 60s. **FAULT:** Amber LED blinks 1-4 times with 3 chirps every 60s. **END OF UNIT LIFE:** Amber LED blinks twice with 2 chirps every 60s. **Temp Range:** 40°F (4.4° C) to 100°F (37.8° C). **Humidity Range:** 10 to 95% relative humidity (RH), non-condensing.

Contains FCC ID SAK-ESP3253. FCC ID: SAK-RGCUARRW

⚠ WARNING: Carbon monoxide (CO) is a colorless, odorless, poisonous gas. You can't taste, see, or smell CO, but it can kill in just minutes. This alarm will sound in a 4-beep pattern if life threatening levels of CO are detected. If the alarm sounds: 1) Immediately evacuate all occupants from the space and go outdoors to fresh air. 2) Call emergency responders (911 or fire department) for help; notify the building or vehicle owner, as necessary.

REPLACE BATTERIES AT LEAST ONCE A YEAR.

⚠ WARNING: **USE ONLY BATTERIES SPECIFIED IN MARKING** (Energizer E91, Gold Peak 15A, Golden Power GL165A). **USE OF A DIFFERENT BATTERY MAY HAVE A DETRIMENTAL EFFECT ON ALARM OPERATION.** NOTE: Do not use lithium batteries in this unit.

Unit will not attach to mounting bracket without batteries installed.

Assembled in China with PCBA from Malaysia

PART NUMBER "A"	COUNTRY OF ORIGIN "B"
XX = MX	Assembled in Mexico

NOTE: AC connector must be removed to replace batteries. Press tab to remove AC connector.

Clean annually. See User Guide for more info.

Wi-Fi

YYYY, MMM, DD

Smoke sensitivity : x.xx +/- x.xx %/ft OBS



38707

DSN: BHSC1714LH000770

L00351HX00 Rev A

 **US**

Intertek

XXXXXX

Model RGCUAR-RW

Combination Photoelectric Smoke/CO Alarm w/ Voice, Wireless Interlink, & Wi-Fi, 120VAC (60Hz, 85mA Max) w/ AA battery backup. Constant exposures to high or low temperatures or high humidity may reduce battery life. **SMOKE ALARM:** 3 Long beeps, repeating. **CO ALARM:** 4 quick beeps, repeating. **STANDBY:** AC power-green LED on. DC only-green LED blinks every 60s. **LOW BATTERY:** Amber LED blinks every 6s with 1 chirp every 60s. **FAULT:** Amber LED blinks 1-4 times with 3 chirps every 60s. **END OF UNIT LIFE:** Amber LED blinks twice with 2 chirps every 60s. **Temp Range:** 40°F (4.4° C) to 100°F (37.8° C). **Humidity Range:** 10 to 95% relative humidity (RH), non-condensing.

Contains FCC ID SAK-ESP3253. FCC ID: SAK-RGCUARRW

⚠ WARNING: Carbon monoxide (CO) is a colorless, odorless, poisonous gas. You can't taste, see, or smell CO, but it can kill in just minutes. This alarm will sound in a 4-beep pattern if life threatening levels of CO are detected. If the alarm sounds: 1) Immediately evacuate all occupants from the space and go outdoors to fresh air. 2) Call emergency responders (911 or fire department) for help; notify the building or vehicle owner, as necessary.

REPLACE BATTERIES AT LEAST ONCE A YEAR.

⚠ WARNING: **USE ONLY BATTERIES SPECIFIED IN MARKING** (Energizer E9L, Gold Peak 15A, Golden Power GL165A). **USE OF A DIFFERENT BATTERY MAY HAVE A DETRIMENTAL EFFECT ON ALARM OPERATION.** NOTE: Do not use lithium batteries in this unit.

Unit will not attach to mounting bracket without batteries installed.

Assembled in Mexico

