



Equipment Photographs

2234-222 (USB)



(Internal)



Equipment Photographs

2234-222 (USB)

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK18041132

Equipment Photographs

2234-222 (USB)

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK18041132

Equipment Photographs

2234-222 (USB)



(Internal)



Equipment Photographs

2234-223 (RS-232)

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK18041132

Equipment Photographs

2234-223 (RS-232)

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK18041132

Equipment Photographs

2234-223 (RS-232)

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK18041132

Equipment Photographs

2234-223 (RS-232)

(Internal)

