9.3.2. 802.11g MODE



LOW CHANNEL 1 BANDEDGE CHAIN 0



OUT-OF-BAND LOW CHANNEL 1 CHAIN 0



LOW CHANNEL 2 BANDEDGE CHAIN 0

OUT-OF-BAND LOW CHANNEL 2 CHAIN 0



IN-BAND REFERENCE LEVEL CHAIN 0



OUT-OF-BAND MID CHANNEL CHAIN 0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 0



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 0



HIGH CHANNEL 11 BANDEDGE CHAIN 0



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1 BANDEDGE CHAIN 1



OUT-OF-BAND LOW CHANNEL 1 CHAIN 1



LOW CHANNEL 2 BANDEDGE CHAIN 1



OUT-OF-BAND LOW CHANNEL 2 CHAIN 1



IN-BAND REFERENCE LEVEL CHAIN 1



OUT-OF-BAND MID CHANNEL CHAIN 1

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 1



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 1



HIGH CHANNEL 11 BANDEDGE CHAIN 1



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 1

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1 BANDEDGE CHAIN 2



OUT-OF-BAND LOW CHANNEL 1 CHAIN 2



LOW CHANNEL 2 BANDEDGE CHAIN 2



OUT-OF-BAND LOW CHANNEL 2 CHAIN 2



IN-BAND REFERENCE LEVEL CHAIN 2



OUT-OF-BAND MID CHANNEL CHAIN 2

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 2



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 2



HIGH CHANNEL 11 BANDEDGE CHAIN 2



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 2

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1 BANDEDGE CHAIN 3



OUT-OF-BAND LOW CHANNEL 1 CHAIN 3



LOW CHANNEL 2 BANDEDGE CHAIN 3



OUT-OF-BAND LOW CHANNEL 2 CHAIN 3



IN-BAND REFERENCE LEVEL CHAIN 3



OUT-OF-BAND MID CHANNEL CHAIN 3

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 3



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 3



HIGH CHANNEL 11 BANDEDGE CHAIN 3



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 3

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.3.3. 802.11n HT20 MODE



LOW CHANNEL 1 BANDEDGE CHAIN 0



OUT-OF-BAND LOW CHANNEL 1 CHAIN 0



LOW CHANNEL 2 BANDEDGE CHAIN 0

OUT-OF-BAND LOW CHANNEL 2 CHAIN 0



IN-BAND REFERENCE LEVEL CHAIN 0



OUT-OF-BAND MID CHANNEL CHAIN 0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 0



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 0



HIGH CHANNEL 11 BANDEDGE CHAIN 0



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LOW CHANNEL 1 BANDEDGE CHAIN 1



OUT-OF-BAND LOW CHANNEL 1 CHAIN 1



LOW CHANNEL 2 BANDEDGE CHAIN 1



OUT-OF-BAND LOW CHANNEL 2 CHAIN 1



IN-BAND REFERENCE LEVEL CHAIN 1



OUT-OF-BAND MID CHANNEL CHAIN 1

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



HIGH CHANNEL 10 BANDEDGE CHAIN 1



OUT-OF-BAND HIGH CHANNEL 10 CHAIN 1



HIGH CHANNEL 11 BANDEDGE CHAIN 1



OUT-OF-BAND HIGH CHANNEL 11 CHAIN 1

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 771-1000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.