

Response to TCB Findings

1. For the SAR testing please supply the calibration data for the E-field probe and the dipole antenna.

Supplied.

2. For the SAR testing please clarify why there is no distribution overlay for configuration 3 on page 19 of the test report.

There was no distribution overlay for configuration 3 on pg 19 because there was no detectable SAR level, as it stated in the table.