

Attachment of accelerometers (4)



If the pipe cannot be accessed directly, accelerometers can also be attached to underground valves. Preferably, they should be lowered into valve access chambers and attached directly to valves. However, chambers may be filled with debris and many users prefer to attach accelerometers to valve keys.