



NTS Silicon Valley
www.nts.com

41039 Boyce Road
Fremont, CA 94538

510-578-3500 Phone
510-440-9525 Fax

National Technical Systems – Silicon Valley TCB

May 4, 2016

RE: FCC ID: SK6-XR630

Attention: Gregory Czumak

Please find our responses to your comments on this application below:

3. Reference is made on p.8 of this c2pc DFS report to results obtained and submitted in the EUT's original DFS report, however, those tests were performed in August 2014. Because the DFS test procedure (KDB905462)D02) has been revised 3 times since the time of testing, it is not clear that the results in the original report remain applicable in demonstrating compliance with the current testing requirements. Please address each of the tests for which the results are being referenced from the original report and explain how the results remain applicable under the current test parameter requirements.

RESPONSE: This device was previous tested and approved against KDB 905462 D01. There were three significant changes made in the test procedure from D01 to D02:

1. Channel loading used during in-service monitoring
2. Bandwidth detection requirement changed from 80% to 100% of the OBW
3. Addition of Bin 1A and 1B radar types

Due to these changes, we felt that only the bandwidth detection and in-service monitoring tests needed to be performed. Based on our experience, the loading in the channel does not affect the channel close/move and non-occupancy. The CAC requirement was unchanged. When we reviewed the original NTS report, we saw that the device met the new bandwidth detection criteria.

A revised test report has been provided.