





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant1-6695-PASS




11AX20MIMO-Ant2-6695-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant1-6895-PASS




11AX20MIMO-Ant2-6895-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX20MIMO-Ant1-6995-PASS




11AX20MIMO-Ant2-6995-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40MIMO-Ant1-5965-PASS




11AX40MIMO-Ant2-5965-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40MIMO-Ant1-6445-PASS




11AX40MIMO-Ant2-6445-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40MIMO-Ant1-6845-PASS




11AX40MIMO-Ant2-6845-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX40MIMO-Ant1-6965-PASS




11AX40MIMO-Ant2-6965-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80MIMO-Ant1-6545-PASS




11AX80MIMO-Ant2-6545-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80MIMO-Ant1-6705-PASS




11AX80MIMO-Ant2-6705-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80MIMO-Ant1-6865-PASS




11AX80MIMO-Ant2-6865-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80MIMO-Ant1-6945-PASS




11AX80MIMO-Ant2-6945-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80MIMO-Ant1-7025-PASS



11AX80MIMO-Ant2-7025-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: InBand Emissions

Test Result

Test Mode	Antenna	Frequency[MHz]	Result	Limit	Verdict
11AX20MIMO	Ant1	5955	See test graph	See test graph	PASS
11AX20MIMO	Ant2	5955	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6175	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6175	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6415	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6415	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6435	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6435	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6475	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6475	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6515	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6515	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6535	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6535	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6695	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6695	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6855	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6855	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6875	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6875	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6895	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6895	See test graph	See test graph	PASS
11AX20MIMO	Ant1	6995	See test graph	See test graph	PASS
11AX20MIMO	Ant2	6995	See test graph	See test graph	PASS
11AX20MIMO	Ant1	7115	See test graph	See test graph	PASS
11AX20MIMO	Ant2	7115	See test graph	See test graph	PASS
11AX40MIMO	Ant1	5965	See test graph	See test graph	PASS
11AX40MIMO	Ant2	5965	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6165	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6165	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6405	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6405	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6445	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6445	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6485	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6485	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6565	See test graph	See test graph	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


11AX40MIMO	Ant2	6565	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6685	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6685	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6845	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6845	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6925	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6925	See test graph	See test graph	PASS
11AX40MIMO	Ant1	6965	See test graph	See test graph	PASS
11AX40MIMO	Ant2	6965	See test graph	See test graph	PASS
11AX40MIMO	Ant1	7085	See test graph	See test graph	PASS
11AX40MIMO	Ant2	7085	See test graph	See test graph	PASS
11AX80MIMO	Ant1	5985	See test graph	See test graph	PASS
11AX80MIMO	Ant2	5985	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6145	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6145	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6385	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6385	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6465	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6465	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6545	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6545	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6625	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6625	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6705	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6705	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6785	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6785	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6865	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6865	See test graph	See test graph	PASS
11AX80MIMO	Ant1	6945	See test graph	See test graph	PASS
11AX80MIMO	Ant2	6945	See test graph	See test graph	PASS
11AX80MIMO	Ant1	7025	See test graph	See test graph	PASS
11AX80MIMO	Ant2	7025	See test graph	See test graph	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Test Graphs




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX20MIMO-Ant1-6175-PASS




NTNV-11AX20MIMO-Ant2-6175-PASS




NTNV-11AX20MIMO-Ant1-6415-PASS




NTNV-11AX20MIMO-Ant2-6415-PASS




NTNV-11AX20MIMO-Ant1-6435-PASS




NTNV-11AX20MIMO-Ant2-6435-PASS




NTNV-11AX20MIMO-Ant1-6475-PASS




NTNV-11AX20MIMO-Ant2-6475-PASS




NTNV-11AX20MIMO-Ant1-6515-PASS




NTNV-11AX20MIMO-Ant2-6515-PASS




NTNV-11AX20MIMO-Ant1-6535-PASS




NTNV-11AX20MIMO-Ant2-6535-PASS




NTNV-11AX20MIMO-Ant1-6695-PASS



NTNV-11AX20MIMO-Ant2-6695-PASS



NTNV-11AX20MIMO-Ant1-6855-PASS




NTNV-11AX20MIMO-Ant2-6855-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX20MIMO-Ant1-6875-PASS



NTNV-11AX20MIMO-Ant2-6875-PASS



NTNV-11AX20MIMO-Ant1-6895-PASS




NTNV-11AX20MIMO-Ant2-6895-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX20MIMO-Ant1-6995-PASS




NTNV-11AX20MIMO-Ant2-6995-PASS




NTNV-11AX20MIMO-Ant1-7115-PASS




NTNV-11AX20MIMO-Ant2-7115-PASS




NTNV-11AX40MIMO-Ant1-5965-PASS




NTNV-11AX40MIMO-Ant2-5965-PASS




NTNV-11AX40MIMO-Ant1-6165-PASS




NTNV-11AX40MIMO-Ant2-6165-PASS




NTNV-11AX40MIMO-Ant1-6405-PASS




NTNV-11AX40MIMO-Ant2-6405-PASS




NTNV-11AX40MIMO-Ant1-6445-PASS



NTNV-11AX40MIMO-Ant2-6445-PASS



NTNV-11AX40MIMO-Ant1-6485-PASS




NTNV-11AX40MIMO-Ant2-6485-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX40MIMO-Ant1-6565-PASS



NTNV-11AX40MIMO-Ant2-6565-PASS



NTNV-11AX40MIMO-Ant1-6685-PASS




NTNV-11AX40MIMO-Ant2-6685-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX40MIMO-Ant1-6845-PASS



NTNV-11AX40MIMO-Ant2-6845-PASS



NTNV-11AX40MIMO-Ant2-6925-PASS




NTNV-11AX40MIMO-Ant1-6925-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX40MIMO-Ant1-6965-PASS




NTNV-11AX40MIMO-Ant2-6965-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX40MIMO-Ant1-7085-PASS



NTNV-11AX40MIMO-Ant2-7085-PASS



NTNV-11AX80MIMO-Ant1-5985-PASS




NTNV-11AX80MIMO-Ant2-5985-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




NTNV-11AX80MIMO-Ant1-6145-PASS




NTNV-11AX80MIMO-Ant2-6145-PASS




NTNV-11AX80MIMO-Ant1-6385-PASS




NTNV-11AX80MIMO-Ant2-6385-PASS




NTNV-11AX80MIMO-Ant1-6465-PASS




NTNV-11AX80MIMO-Ant2-6465-PASS




NTNV-11AX80MIMO-Ant1-6545-PASS




NTNV-11AX80MIMO-Ant2-6545-PASS




NTNV-11AX80MIMO-Ant1-6625-PASS




NTNV-11AX80MIMO-Ant2-6625-PASS




NTNV-11AX80MIMO-Ant1-6705-PASS



NTNV-11AX80MIMO-Ant2-6705-PASS



NTNV-11AX80MIMO-Ant1-6785-PASS




NTNV-11AX80MIMO-Ant2-6785-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX80MIMO-Ant2-6865-PASS




NTNV-11AX80MIMO-Ant1-6865-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX80MIMO-Ant1-6945-PASS




NTNV-11AX80MIMO-Ant2-6945-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX80MIMO-Ant1-7025-PASS



NTNV-11AX80MIMO-Ant2-7025-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix F: CBP_Incumbent Single Test

Test Result


TestMode	Antenna	Channel	testFreq	Result	Gain	AujResult	Limit [dBm]	Verdict
11AX20SISO	Ant1	5955	5955	-59.03	3.32	-62.35	-62	PASS
11AX20SISO	Ant1	6435	6435	-59.07	3.32	-62.39	-62	PASS
11AX20SISO	Ant1	6535	6535	-58.93	3.32	-62.25	-62	PASS
11AX20SISO	Ant1	7115	7115	-58.99	3.32	-62.31	-62	PASS
11AX80SISO	Ant1	5985	5950	-58.95	3.32	-62.27	-62	PASS
11AX80SISO	Ant1	5985	5985	-59.52	3.32	-62.84	-62	PASS
11AX80SISO	Ant1	5985	6020	-58.9	3.32	-62.22	-62	PASS
11AX80SISO	Ant1	6465	6430	-59.01	3.32	-62.33	-62	PASS
11AX80SISO	Ant1	6465	6465	-59.14	3.32	-62.46	-62	PASS
11AX80SISO	Ant1	6465	6500	-58.94	3.32	-62.26	-62	PASS
11AX80SISO	Ant1	6865	6830	-59.01	3.32	-62.33	-62	PASS
11AX80SISO	Ant1	6865	6865	-58.96	3.32	-62.28	-62	PASS
11AX80SISO	Ant1	6865	6900	-58.9	3.32	-62.22	-62	PASS
11AX80SISO	Ant1	7025	6990	-59.09	3.32	-62.41	-62	PASS
11AX80SISO	Ant1	7025	7025	-59.05	3.32	-62.37	-62	PASS
11AX80SISO	Ant1	7025	7060	-58.97	3.32	-62.29	-62	PASS

Note: 3.32dBi is the minimum antenna gain for the entire frequency band 5925~7125MHz, and final antenna gain is already included antenna cable loss.

Test Result



11AX20SISO-Ant1-5955-5955-PASS




11AX20SISO-Ant1-6435-6435-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80SISO-Ant1-5985-6020-PASS




11AX80SISO-Ant1-6465-6430-PASS



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AX80SISO-Ant1-6865-6900-PASS




11AX80SISO-Ant1-7025-6990-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix H: Contention Based Protocol

Test Result

Test Mode	Antenna	Channel	Test Name	Test Freq	UEStatus	TL	Gain	AjPower	Limit [dBm]	Verdict
11AX20SISO	Ant1	5955	Center	5955	OFF	-64.6	3.32	-67.92	-62	PASS
11AX20SISO	Ant1	5955	Center	5955	Minimal	-75.6	3.32	-78.92	-62	PASS
11AX20SISO	Ant1	5955	Center	5955	ON	-83.6	3.32	-86.92	-62	PASS
11AX20SISO	Ant1	6435	Center	6435	OFF	-66.68	3.32	-70	-62	PASS
11AX20SISO	Ant1	6435	Center	6435	Minimal	-69.68	3.32	-73	-62	PASS
11AX20SISO	Ant1	6435	Center	6435	ON	-83.68	3.32	-87	-62	PASS
11AX20SISO	Ant1	6535	Center	6535	OFF	-76.6	3.32	-79.92	-62	PASS
11AX20SISO	Ant1	6535	Center	6535	Minimal	-78.6	3.32	-81.92	-62	PASS
11AX20SISO	Ant1	6535	Center	6535	ON	-83.6	3.32	-86.92	-62	PASS
11AX20SISO	Ant1	7115	Center	7115	OFF	-74.6	3.32	-77.92	-62	PASS
11AX20SISO	Ant1	7115	Center	7115	Minimal	-75.6	3.32	-78.92	-62	PASS
11AX20SISO	Ant1	7115	Center	7115	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	5985	Low	5950	OFF	-62.6	3.32	-65.92	-62	PASS
11AX80SISO	Ant1	5985	Center	5985	OFF	-62.6	3.32	-65.92	-62	PASS
11AX80SISO	Ant1	5985	High	6020	OFF	-63.6	3.32	-66.92	-62	PASS
11AX80SISO	Ant1	5985	Low	5950	Minimal	-65.6	3.32	-68.92	-62	PASS
11AX80SISO	Ant1	5985	Center	5985	Minimal	-66.6	3.32	-69.92	-62	PASS
11AX80SISO	Ant1	5985	High	6020	Minimal	-72.6	3.32	-75.92	-62	PASS
11AX80SISO	Ant1	5985	Low	5950	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	5985	Center	5985	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	5985	High	6020	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	6465	Low	6430	OFF	-62.68	3.32	-66	-62	PASS
11AX80SISO	Ant1	6465	Center	6465	OFF	-60.68	3.32	-64	-62	PASS
11AX80SISO	Ant1	6465	High	6500	OFF	-62.68	3.32	-66	-62	PASS
11AX80SISO	Ant1	6465	Low	6430	Minimal	-65.68	3.32	-69	-62	PASS
11AX80SISO	Ant1	6465	Center	6465	Minimal	-63.68	3.32	-67	-62	PASS
11AX80SISO	Ant1	6465	High	6500	Minimal	-74.68	3.32	-78	-62	PASS
11AX80SISO	Ant1	6465	Low	6430	ON	-83.68	3.32	-87	-62	PASS
11AX80SISO	Ant1	6465	Center	6465	ON	-83.68	3.32	-87	-62	PASS
11AX80SISO	Ant1	6465	High	6500	ON	-83.68	3.32	-87	-62	PASS
11AX80SISO	Ant1	6865	Low	6830	OFF	-62.6	3.32	-65.92	-62	PASS
11AX80SISO	Ant1	6865	Center	6865	OFF	-61.8	3.32	-65.12	-62	PASS
11AX80SISO	Ant1	6865	High	6900	OFF	-61.6	3.32	-64.92	-62	PASS
11AX80SISO	Ant1	6865	Low	6830	Minimal	-68.6	3.32	-71.92	-62	PASS
11AX80SISO	Ant1	6865	Center	6865	Minimal	-75.6	3.32	-78.92	-62	PASS
11AX80SISO	Ant1	6865	High	6900	Minimal	-64.6	3.32	-67.92	-62	PASS
11AX80SISO	Ant1	6865	Low	6830	ON	-83.6	3.32	-86.92	-62	PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX80SISO	Ant1	6865	Center	6865	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	6865	High	6900	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	7025	Low	6990	OFF	-62.6	3.32	-65.92	-62	PASS
11AX80SISO	Ant1	7025	Center	7025	OFF	-59.6	3.32	-62.92	-62	PASS
11AX80SISO	Ant1	7025	High	7060	OFF	-61.6	3.32	-64.92	-62	PASS
11AX80SISO	Ant1	7025	Low	6990	Minimal	-65.6	3.32	-68.92	-62	PASS
11AX80SISO	Ant1	7025	Center	7025	Minimal	-73.6	3.32	-76.92	-62	PASS
11AX80SISO	Ant1	7025	High	7060	Minimal	-64.6	3.32	-67.92	-62	PASS
11AX80SISO	Ant1	7025	Low	6990	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	7025	Center	7025	ON	-83.6	3.32	-86.92	-62	PASS
11AX80SISO	Ant1	7025	High	7060	ON	-83.6	3.32	-86.92	-62	PASS

Test Mode	Antenna	Frequency [MHz]	AWGN Location	AWGN Frequency (MHz)	Test time	Is Detected	Verdict	Detection Probability
11AX20SISO	Ant1	5955	Center	5955	1	Yes	PASS	100%
11AX20SISO	Ant1	5955	Center	5955	2	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	3	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	4	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	5	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	6	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	7	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	8	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	9	Yes	PASS	
11AX20SISO	Ant1	5955	Center	5955	10	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	1	Yes	PASS	100%
11AX20SISO	Ant1	6435	Center	6435	2	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	3	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	4	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	5	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	6	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	7	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	8	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	9	Yes	PASS	
11AX20SISO	Ant1	6435	Center	6435	10	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	1	Yes	PASS	100%
11AX20SISO	Ant1	6535	Center	6535	2	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	3	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	4	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	5	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	6	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	7	Yes	PASS	

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX20SISO	Ant1	6535	Center	6535	8	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	9	Yes	PASS	
11AX20SISO	Ant1	6535	Center	6535	10	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	1	Yes	PASS	100%
11AX20SISO	Ant1	7115	Center	7115	2	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	3	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	4	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	5	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	6	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	7	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	8	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	9	Yes	PASS	
11AX20SISO	Ant1	7115	Center	7115	10	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	1	Yes	PASS	100%
11AX80SISO	Ant1	5985	Low	5950	2	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	3	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	4	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	5	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	6	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	7	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	8	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	9	Yes	PASS	
11AX80SISO	Ant1	5985	Low	5950	10	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	1	Yes	PASS	100%
11AX80SISO	Ant1	5985	Center	5985	2	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	3	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	4	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	5	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	6	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	7	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	8	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	9	Yes	PASS	
11AX80SISO	Ant1	5985	Center	5985	10	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	1	Yes	PASS	100%
11AX80SISO	Ant1	5985	High	6020	2	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	3	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	4	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	5	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	6	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	7	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	8	Yes	PASS	
11AX80SISO	Ant1	5985	High	6020	9	Yes	PASS	

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX80SISO	Ant1	5985	High	6020	10	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	1	Yes	PASS	100%
11AX80SISO	Ant1	6465	Low	6430	2	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	3	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	4	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	5	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	6	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	7	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	8	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	9	Yes	PASS	
11AX80SISO	Ant1	6465	Low	6430	10	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	1	Yes	PASS	100%
11AX80SISO	Ant1	6465	Center	6465	2	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	3	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	4	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	5	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	6	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	7	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	8	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	9	Yes	PASS	
11AX80SISO	Ant1	6465	Center	6465	10	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	1	Yes	PASS	100%
11AX80SISO	Ant1	6465	High	6500	2	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	3	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	4	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	5	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	6	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	7	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	8	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	9	Yes	PASS	
11AX80SISO	Ant1	6465	High	6500	10	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	1	Yes	PASS	100%
11AX80SISO	Ant1	6865	Low	6830	2	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	3	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	4	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	5	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	6	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	7	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	8	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	9	Yes	PASS	
11AX80SISO	Ant1	6865	Low	6830	10	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	1	Yes	PASS	100%

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX80SISO	Ant1	6865	Center	6865	2	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	3	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	4	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	5	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	6	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	7	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	8	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	9	Yes	PASS	
11AX80SISO	Ant1	6865	Center	6865	10	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	1	Yes	PASS	100%
11AX80SISO	Ant1	6865	High	6900	2	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	3	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	4	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	5	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	6	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	7	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	8	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	9	Yes	PASS	
11AX80SISO	Ant1	6865	High	6900	10	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	1	Yes	PASS	100%
11AX80SISO	Ant1	7025	Low	6990	2	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	3	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	4	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	5	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	6	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	7	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	8	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	9	Yes	PASS	
11AX80SISO	Ant1	7025	Low	6990	10	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	1	Yes	PASS	100%
11AX80SISO	Ant1	7025	Center	7025	2	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	3	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	4	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	5	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	6	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	7	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	8	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	9	Yes	PASS	
11AX80SISO	Ant1	7025	Center	7025	10	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	1	Yes	PASS	100%
11AX80SISO	Ant1	7025	High	7060	2	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	3	Yes	PASS	

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11AX80SISO	Ant1	7025	High	7060	4	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	5	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	6	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	7	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	8	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	9	Yes	PASS	
11AX80SISO	Ant1	7025	High	7060	10	Yes	PASS	

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com