

附件 A

Bluetooth GPS Quick Tips

1. Activate Bluetooth function of your PDA / PC

Prior to activating the Bluetooth function of your PDA / PC, make sure the device is equipped with Bluetooth function, and the driver software has been installed.

2. Activate Bluetooth Manager & Established New Connections

Illustrations using HP 2100 PDA as follows:

- 1.First, find the device with which you wish to establish connection.
- 2.Open “Bluetooth Manager” on your pocket pc.
- 3.Press “New”.
- 4.Press "Connect”.



2.1




2.2



2.3




2.4



2.5



2.5



2.6

At this point, Bluetooth GPS connection has been successfully established



Established connection

2.7

附件 B

USER Database Utility

1. The software support Windows XP
2. Support WGS84 Longitude / Latitude input.
- Step1 : Please use G-Mouse mode
- Step2 : Execute “ User_DB_Modify.exe ” .
- Step3 : Choose com port and choose “ Open COM Port ” button to open com port.
- Step4 : Choose “ Load user database from device ” button to load user database
- Step5 : Choose “ Read next page ” or “ Read previous page ” to read more data.
- Step6 : if you had modified data on one page, choose “ Save this page ” button to save page.
- Step7 : If you sure update your database to device ,please choose “ Exit and write to Device ” button to update flash and exit application software.
- Step8 : If you do not want to update your database to device ,please choose “ Exit ” button to exit application software.
- Step9 : Disconnect device ,and device auto change to suspend mode.

Note :

Speed :

Unit = mile or kilometer

Speed : 0 ~ 999

or

Speed : NULL (don ' t have over speed alarm)

Direction :

Camera Direction : 0 ~ 359

or

Camera Direction : NULL (not direction Camera)

Type : 0 = fixed Camera

1 = mobile Camera