




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54

4 Peak-Average Ratio

Band	Carrier frequency (MHz)	Channel	BW (MHz)	RB Size	RB Offset	QPSK	16-QAM	64-QAM
66	1710.7	131979	1.4	1	5	Fig.1	Fig.2	Fig.3
66	1710.7	131979	1.4	6	0	Fig.4	Fig.5	Fig.6
66	1755	132422	1.4	1	5	Fig.7	Fig.8	Fig.9
66	1755	132422	1.4	6	0	Fig.10	Fig.11	Fig.12
66	1779.3	132665	1.4	1	5	Fig.13	Fig.14	Fig.15
66	1779.3	132665	1.4	6	0	Fig.16	Fig.17	Fig.18
66	1711.5	131987	3	1	14	Fig.19	Fig.20	Fig.21
66	1711.5	131987	3	15	0	Fig.22	Fig.23	Fig.24
66	1755	132422	3	1	14	Fig.25	Fig.26	Fig.27
66	1755	132422	3	15	0	Fig.28	Fig.29	Fig.30
66	1778.5	132657	3	1	14	Fig.31	Fig.32	Fig.33
66	1778.5	132657	3	15	0	Fig.34	Fig.35	Fig.36
66	1712.5	131997	5	1	24	Fig.37	Fig.38	Fig.39
66	1712.5	131997	5	25	0	Fig.40	Fig.41	Fig.42
66	1755	132422	5	1	24	Fig.43	Fig.44	Fig.45
66	1755	132422	5	25	0	Fig.46	Fig.47	Fig.48
66	1777.5	132647	5	1	24	Fig.49	Fig.50	Fig.51
66	1777.5	132647	5	25	0	Fig.52	Fig.53	Fig.54
66	1715	132022	10	1	49	Fig.55	Fig.56	Fig.57
66	1715	132022	10	50	0	Fig.58	Fig.59	Fig.60
66	1755	132422	10	1	49	Fig.61	Fig.62	Fig.63
66	1755	132422	10	50	0	Fig.64	Fig.65	Fig.66
66	1775	132622	10	1	49	Fig.67	Fig.68	Fig.69
66	1775	132622	10	50	0	Fig.70	Fig.71	Fig.72
66	1717.5	132047	15	1	74	Fig.73	Fig.74	Fig.75
66	1717.5	132047	15	75	0	Fig.76	Fig.77	Fig.78
66	1755	132422	15	1	74	Fig.79	Fig.80	Fig.81
66	1755	132422	15	75	0	Fig.82	Fig.83	Fig.84
66	1772.5	132597	15	1	74	Fig.85	Fig.86	Fig.87
66	1772.5	132597	15	75	0	Fig.88	Fig.89	Fig.90
66	1720	132072	20	1	99	Fig.91	Fig.92	Fig.93
66	1720	132072	20	100	0	Fig.94	Fig.95	Fig.96
66	1755	132422	20	1	99	Fig.97	Fig.98	Fig.99
66	1755	132422	20	100	0	Fig.100	Fig.101	Fig.102
66	1770	132572	20	1	99	Fig.103	Fig.104	Fig.105
66	1770	132572	20	100	0	Fig.106	Fig.107	Fig.108




Fig.1




Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8




Fig.9




Fig.10




Fig.11




Fig.12




Fig.13




Fig.14




Fig.15




Fig.16




Fig.17




Fig.18




Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24




Fig.25




Fig.26




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36