Internal View of EUT-77



Internal View of EUT-78



Internal View of EUT-79

Internal View of EUT-80

Internal View of EUT-81



Internal View of EUT-82



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-83



Internal View of EUT-84



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-85



Internal View of EUT-86



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-87



Internal View of EUT-88



Internal View of EUT-89(ANT5)

Internal View of EUT-90(ANT5)

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-91 （ANT5）



Internal View of EUT-92 (ANT5)

Internal View of EUT-93(ANT4)

Internal View of EUT-94(ANT4)



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-95(ANT4)

Internal View of EUT-96(ANT4)

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-97



Internal View of EUT-98

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-99(ANT2)



Internal View of EUT-100(ANT2)



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-101(ANT2)



Internal View of EUT-102(ANT2)



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-103(ANT3)

Internal View of EUT-104(ANT3)



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.