


11N20MIMO_Ant2_5745




11N20MIMO_Ant3_5745




11N20MIMO_Ant2_5785


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N20MIMO_Ant3_5785




11N20MIMO_Ant2_5825




11N20MIMO_Ant3_5825


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N40MIMO_Ant2_5190




11N40MIMO_Ant3_5190




11N40MIMO_Ant2_5230


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N40MIMO_Ant3_5230




11N40MIMO_Ant2_5755




11N40MIMO_Ant3_5755


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N40MIMO_Ant2_5795




11N40MIMO_Ant3_5795




11AC80MIMO_Ant2_5210


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AC80MIMO_Ant3_5210




11AC80MIMO_Ant2_5775




11AC80MIMO_Ant3_5775


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX20MIMO_Ant2_5180




11AX20MIMO_Ant3_5180




11AX20MIMO_Ant2_5200


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX20MIMO_Ant3_5200




11AX20MIMO_Ant2_5240




11AX20MIMO_Ant3_5240


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX20MIMO_Ant2_5745




11AX20MIMO_Ant3_5745




11AX20MIMO_Ant2_5785


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX20MIMO_Ant3_5785




11AX20MIMO_Ant2_5825




11AX20MIMO_Ant3_5825


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX40MIMO_Ant2_5190




11AX40MIMO_Ant3_5190




11AX40MIMO_Ant2_5230


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX40MIMO_Ant3_5230




11AX40MIMO_Ant2_5755




11AX40MIMO_Ant3_5755


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX40MIMO_Ant2_5795




11AX40MIMO_Ant3_5795




11AX80MIMO_Ant2_5210


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11AX80MIMO_Ant3_5210




11AX80MIMO_Ant2_5775




11AX80MIMO_Ant3_5775


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*

## 11.3. APPENDIX C: MIN EMISSION BANDWIDTH

### 11.3.1. Test Result

| Test Mode | Antenna | Frequency [MHz] | 6db EBW [MHz] | FL[MHz] | FH[MHz] | Limit[MHz] | Verdict |
|---|---|---|---|---|---|---|---|
| 11A | Ant2 | 5745 | 16.120 | 5737.040 | 5753.160 | ≥0.5 | PASS |
| | Ant3 | 5745 | 16.320 | 5736.840 | 5753.160 | ≥0.5 | PASS |
| | Ant2 | 5785 | 16.000 | 5776.880 | 5792.880 | ≥0.5 | PASS |
| | Ant3 | 5785 | 16.000 | 5776.880 | 5792.880 | ≥0.5 | PASS |
| | Ant2 | 5825 | 15.680 | 5816.880 | 5832.560 | ≥0.5 | PASS |
| | Ant3 | 5825 | 15.160 | 5817.480 | 5832.640 | ≥0.5 | PASS |
| 11N20MIMO | Ant2 | 5745 | 16.960 | 5736.240 | 5753.200 | ≥0.5 | PASS |
| | Ant3 | 5745 | 17.200 | 5736.600 | 5753.800 | ≥0.5 | PASS |
| | Ant2 | 5785 | 17.520 | 5776.280 | 5793.800 | ≥0.5 | PASS |
| | Ant3 | 5785 | 17.520 | 5776.280 | 5793.800 | ≥0.5 | PASS |
| | Ant2 | 5825 | 16.760 | 5816.240 | 5833.000 | ≥0.5 | PASS |
| | Ant3 | 5825 | 16.520 | 5816.520 | 5833.040 | ≥0.5 | PASS |
| 11N40MIMO | Ant2 | 5755 | 36.080 | 5736.840 | 5772.920 | ≥0.5 | PASS |
| | Ant3 | 5755 | 36.240 | 5736.920 | 5773.160 | ≥0.5 | PASS |
| | Ant2 | 5795 | 35.680 | 5776.840 | 5812.520 | ≥0.5 | PASS |
| | Ant3 | 5795 | 36.320 | 5776.840 | 5813.160 | ≥0.5 | PASS |
| 11AC80MIMO | Ant2 | 5775 | 64.960 | 5745.080 | 5810.040 | ≥0.5 | PASS |
| | Ant3 | 5775 | 63.200 | 5745.560 | 5808.760 | ≥0.5 | PASS |
| 11AX20MIMO | Ant2 | 5745 | 18.520 | 5735.640 | 5754.160 | ≥0.5 | PASS |
| | Ant3 | 5745 | 18.520 | 5735.880 | 5754.400 | ≥0.5 | PASS |
| | Ant2 | 5785 | 18.640 | 5775.760 | 5794.400 | ≥0.5 | PASS |
| | Ant3 | 5785 | 17.600 | 5776.200 | 5793.800 | ≥0.5 | PASS |
| | Ant2 | 5825 | 18.160 | 5815.640 | 5833.800 | ≥0.5 | PASS |
| | Ant3 | 5825 | 18.480 | 5816.040 | 5834.520 | ≥0.5 | PASS |
| 11AX40MIMO | Ant2 | 5755 | 37.280 | 5736.600 | 5773.880 | ≥0.5 | PASS |
| | Ant3 | 5755 | 36.960 | 5736.360 | 5773.320 | ≥0.5 | PASS |
| | Ant2 | 5795 | 36.880 | 5776.120 | 5813.000 | ≥0.5 | PASS |
| | Ant3 | 5795 | 36.560 | 5776.600 | 5813.160 | ≥0.5 | PASS |
| 11AX80MIMO | Ant2 | 5775 | 72.000 | 5738.040 | 5810.040 | ≥0.5 | PASS |
| | Ant3 | 5775 | 72.320 | 5736.280 | 5808.600 | ≥0.5 | PASS |


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*

### 11.3.2. Test Graphs

11A_Ant2_5745




11A_Ant3_5745




11A_Ant2_5785


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11A_Ant3_5785




11A_Ant2_5825

11A_Ant3_5825


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N20MIMO_Ant2_5745




11N20MIMO_Ant3_5745




11N20MIMO_Ant2_5785


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N20MIMO_Ant3_5785




11N20MIMO_Ant2_5825




11N20MIMO_Ant3_5825


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*




11N40MIMO_Ant2_5755

11N40MIMO_Ant3_5755




11N40MIMO_Ant2_5795


*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*